

PMA-1000 Probes

	A Diameter	B Length	C Radius	Order Number
	.250"	.250"	.250"	310
	.375"	.156"	.437"	306
	.500"	.187"	.562"	311
	.625"	.187"	.813"	316
	.750"	.218"	1.00"	319

	.125"	.250"	.187"	405
	.1875"	.250"	.187"	407
	.250"	.250"	.218"	409
	.3125"	.250"	.250"	411
	.375"	.312"	.205"	412
	.437"	.343"	.250"	413
.500"	.375"	.250"	414	

	3mm	.250"	.187"	400-3
	4mm	.250"	.187"	400-4
	5mm	.250"	.187"	400-5
	6mm	.250"	.218"	400-6
	7mm	.250"	.234"	400-7
	8mm	.250"	.250"	400-8
	9mm	.312"	.250"	400-9
	10mm	.312"	.250"	400-10
	11mm	.343"	.250"	400-11
	12mm	.343"	.250"	400-12

	.187"	.750"	.187"	808
	.187"	.750"	.187"	308
	.250"	.250"	Flat	361
	.375"	.156"	Flat	358
	.500"	.187"	Flat	317
	.625"	.187"	Flat	365

	A Diameter	B Length	C Length	Order Number
	.060"	.500"	.800"	525&526

	A Diameter	B Length	Order Number
	.750"	.218"	366
	1.000"	.218"	367